



**Confidence & Quality**

**Automotive Spare Parts**







*Solutions*

**DAEWOO**

**RUBBER HOSE**

[www.motortec.com.tr](http://www.motortec.com.tr)

**Motortec International Auto Spare Parts Group**

PICTURE	CODE	MODEL	OEM	DISCREPTION
	MB 92100	RACER-NEXIA LANOS 1.8 KALOS (1995-1997)	90409191-96461003	OIL HOSE
	MB 92101	RACER-NEXIA (1995-1998)	5038A4-1339628080	HOSE
	MB 92102	LANOS 1.5 (1997-2004)	96351640	GAP HOSE
	MB 92103	ESPERO 1.8-2.0 (1991-1999)	96180848	ENGINE AIR HOSE
	MB 92104	RACER-CIELO (1996-1999)	96180322-96143403	RADIATOR UPPER HOSE
	MB 92105	LANOS	96351259-96182268	RADIATOR UPPER HOSE