



Confidence & Quality

Automotive Spare Parts

















Solutions





HONDA

RUBBER HOSE

www.motortec.com.tr

Motortec International Auto Spare Parts Group

PICTURE	CODE	MODEL	OEM	DISCREPTION
	MB 76100	CIVIC	19501 P08000	RADIATOR UPPER HOSE
	MB 76101	CIVIC	19502 P2A000	RADIATOR LOWER HOSE
	MB 76102	CIVIC	79721SR3000	HEATER HOSE
	MB 76103	CIVIC	19508P08000	HEATER HOSE
	MB 76104	CIVIC	19501-PM3000	RADIATOR UPPER HOSE
	MB 76105	CIVIC	19502-PM3000	RADIATOR LOWER HOSE
	MB 76106	CIVIC	19501-RNA-A01	RADIATOR UPPER HOSE
	MB 76107	CIVIC	19502-RNAA01	RADIATOR LOWER HOSE
	MB 76108	CIVIC	19502-PA1000	RADIATOR UPPER HOSE
	MB 76109	CIVIC	19501-PA1010	RADIATOR LOWER HOSE
	MB 76110	ACCORD	19501PT0000	RADIATOR UPPER HOSE
	MB 76111	ACCORD	19502PT0000	RADIATOR LOWER HOSE
	MB 76112	CIVIC HB 1.3 (1989-1991) Coupe 1.5-1.6 (1987-2001)	1901 P08000	RADIATOR UPPER HOSE
	MB 76113	CIVIC 1.3 16V(1988-1995)	19502 P03000	RADIATOR LOWER HOSE
	MB 76114	ACCORD	6112689	RADIATOR UPPER HOSE
	MB 76115	ACCORD		RADIATOR LOWER HOSE

	MB 76116	ACCORD	19505RBA000	RADIATOR LOWER HOSE
	MB 76117	CIVIC	19501RNAA01	RADIATOR UPPER HOSE
	MB 76118	ACCORD	19501RBA000	RADIATOR UPPER HOSE
	MB 76119	ACCORD	19502P8AA00	RADIATOR LOWER HOSE

3

Bu belgede kullanılan araç marka, model, logo, OEM numaraları, vb. bilgiler referans amaçlı kullanılmıştır.
It's written for comperement the original numbers of aim on the catalogue.