



Confidence & Quality

Automotive Spare Parts

Solutions

KIA

RUBBER HOSE

www.motortec.com.tr

Motortec International Auto Spare Parts Group

PICTURE	CODE	MODEL	OEM	DISCREPTION
	MB 96100	CERES 2200 CC	OK62015186Y	RADIATOR UPPER HOSE
	MB 96101	CERES 2200 CC	OK62015185Y	RADIATOR LOWER HOSE
	MB 96102	CERES 2400 CC	OK86215186Y	RADIATOR UPPER HOSE
	MB 96103	CERES 2400 CC	OK86215185Y	RADIATOR LOWER HOSE
	MB 96104	BONGO	OK6015186	RADIATOR UPPER HOSE
	MB 96105	BONGO	OK6015185	RADIATOR LOWER HOSE
	MB 96106	RIO-ACCENT BLUE VELOSTER	254121R100	RADIATOR LOWER HOSE
	MB 96107	RIO II -ACCENT-ERA	254111E000	RADIATOR UPPER HOSE
	MB 96108	PICANTO - MORNING	310361Y000	