



**Confidence & Quality**

**Automotive Spare Parts**

*Solutions*

**SUZUKI**

**RUBBER HOSE**

[www.motortec.com.tr](http://www.motortec.com.tr)

**Motortec International Auto Spare Parts Group**

PICTURE	CODE	MODEL	OEM	DISCREPTION
	MB 91100	BELANO (1995-2001)	1785260G10	RADIATOR UPPER HOSE
	MB 91101	BELANO (1995-2001)	1118973000	RADIATOR LOWER HOSE
	MB 91102	CARRY	1784185202-1784776A30	RADIATOR UPPER HOSE
	MB 91103	CARRY	1785152202-1785777A10	RADIATOR LOWER HOSE
	MB 91104	AERIO (2002-2003)	1785454G00	RADIATOR LOWER HOSE
	MB 91105	AERIO(2002-2003)	1785254G00	RADIATOR UPPER HOSE
	MB 91106	LIANA	1787154G00	HEATER HOSE
	MB 91107	LIANA	1787254G00	HEATER HOSE
	MB 91108	SWIFT	1785263J00	RADIATOR UPPER HOSE
	MB 91109	BALENO-ESTEEM	8924160G20	HOSE FUEL TANK FILLING
	MB 91110	BALENO	1785465G00	RADIATOR LOWER HOSE
	MB 91111	IPON-TROPER	8944752051	HEATER HOSE